TO BE FILLED BY THE INSPECTING OFFICER (Assistant Engineer / Assistant Executive Engineer)	
Name of School CHINMAYA	VIDYALAYA Banhangad
Name of the Officer	Roy. Mathew. Kashangud.
2. Location	Kanhanguel. 15.09.2022 to 31.05.2023.
3. Period for which the certificate is issued  GF+FF+SF	26.70× 8.45 × 3.60 KCC 90(ass +0)h
4. Types of building — do -	41.00 x 8.60 x 3.60 RCC 6class + late 15.50 x 8 60 x 3.60 RCC 6class.
5. Nature of defect if any	24.00 × 8.60 × 3.60 Ree 6 class + la
a) Foundation and basement	
b) Superstructure	
c) Doors and windows	
d) Wood work wrought and put up	NIL
e) Roof	
f) Flooring	
g) Miscellaneous (Cracks if any)	
Any major defects noticed which will render the building unsafe in any manner	No.
7. Whether maintenance work have been done properly	Fes
8. Whether the structure is sound or not for conducting classes.	es. Under normal weather and wind Conditions
Note: 1 The Stability of the structure should be examined wind exposure to flood etc.	nined also with reference to location altitude intensity of
<ol> <li>Any additional observation deemed necessaring the Certificate.</li> </ol>	ary for the Certificate, may be furnished separat∋ly with
Certified that the School was inspected to be, fit / unfit to conduct classes for the period for the re	by me on

Place: Hayhongad

Designation Date....

ROY MATHEW
PEN No: 334455
ASSISTANT ENGINEER, KARHANGAD MUNICIPALITY
NAMIHANGAD (P.O) - 671315